



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A. San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 5/8/19

Preuss School

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1301057	04/18/19	06:33 AM	SAMPLE 1	3710020-CHI-A	< 5	ug/L
W1301058	04/18/19	06:35 AM	SAMPLE 2	3710020-CHI-B	< 5	ug/L
W1301059	04/18/19	06:38 AM	SAMPLE 3	3710020-CHI-C	< 5	ug/L
W1301060	04/18/19	06:42 AM	SAMPLE 4	3710020-CHI-D	< 5	ug/L
W1301061	04/18/19	06:49 AM	SAMPLE 5	3710020-CHI-E	< 5	ug/L

Source Source Description

- SAMPLE 1 Main BLDG exterior, North end, two wall mount fixtures, lower right bubbler
- SAMPLE 2 A BLDG exterior, south side between Boys RR A107 and Staff RR A106, two wall mount fixtures, lower right bubbler
- SAMPLE 3 C BLDG exterior, north side, between rooms C102 and C101, three triple fixtures, 4th bubbler from the right
- SAMPLE 4 C BLDG exterior, south side between C109 and C108, two wall mount fixtures, lower right bubbler
- SAMPLE 5 Main BLDG interior hallway, two wall mount fixtures, upper left bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Tom Burger, Associate Chemist